

Kentatsu air conditioners KSGH/KSRH21CFDN1, KSGH/KSRH26CFDN1, KSGH/KSRH35CFDN1, KSGH/KSRH53CFDN1, KSGH/KSRH21HFDN1, KSGH/KSRH26HFDN1, KSGH/KSRH35HFDN1, KSGH/KSRH53HFDN1

E1 - EEPROM error (non-volatile memory on the board)

E2 - zero crossing error

E3 - abnormal fan speed

E4 - compressor current protection has been activated 4 times

E5 - indoor temperature sensor closed / torn off

E6 - evaporator temperature sensor closed / broken